Security Advisory: Vigor 3900, 2960, 300B Router Vulnerability (July 2020)

255 Keira Tait Wed, Jul 29, 2020 Draytek Routers 912

Draytek have released a critical firmware update for the Vigor 3900 / 2960 / 300B. We recommend that you update the firmware to 1.5.1.1. The update is for Vigor 3900, 2960 and 300B only and does not affect any other Draytek product.

More information regarding security update is available here:

https://www.draytek.co.uk/support/security-advisories/kb-advisory-jun20

As with any such update, it is important that you upgrade any applicable models under your control immediately.

Online URL: https://kb2.ic.uk/article.php?id=255